Qty:

Date:

Friday, 12/06/2009 9:54:09 AM

User: Julie Dawson

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 48534

Estimate Number

: 14001

P.O. Number This Issue

Prsht Rev.

First Issue

Written By

Previous Run

: 12/06/2009

: NC

: //

: 48372

: SMALL /MED FAB Type

S.O. No. :

Part Number

Drawing Name

: D26904

Drawing Number

- D2690 REV. B2

: 23/06/2009

Project Number

: N/A : B2

Drawing Revision

Material **Due Date**

: LANYARD ASSEMBLY

10 Um:

Each

Checked & Approved By

Comment

С : Est:

09.06.03

new issue

EC verified by:DD

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

CBL460

Loop Sleeve

20.0000 Each(s)

Comment: Qty.:

2.0000 Each(s)/Unit Loop Sleeve

Pick:

Part Number **CBL-460**

Description Loop Sleeve

Total:

Batch

2.0

CBL1240

Qty

2



Comment: Qty.:

0.5500 f(s)/Unit

Total: 5.5000 f(s)

Cable Pick:

Qty

Part Number CBL-1240

Description

Cable

3.0

6.25" SMALL FAB 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per Dwg D2690

QC5

4.0

INSPECT WORK TO CURREN

Comment: INSPECT WORK TO CURRENT STEP

5.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:



Page 1

Form: rproces

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	ES						
DATE STEP		PRO	OCEDURE CHAN	IGE	By Date Qty Approva			Approval Chief Eng / Prod Mar	Approval QC Inspector		
								- Too wag			
Part No	•	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	A:	Date:			
		solution:									
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR)					
DATE	STEP	Description of NC	Corrective Action Section			Verification			Approval		
DATE	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Approval Chief Eng	QC Inspector			
	1		1 1					1			

NOTE: Date & initial all entries

Date: User: Friday, 12/06/2009 9:54:10 AM

Julie Dawson

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LANYARD ASSEMBLY

Job Number: 48534

Part Number: D26904

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21



FINAL INSPECTION/W/O RELEASE

11 11 09/06/24 A

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



C209106124

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
					L.					

Part No:		PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
D.475	STEP	Description of NC	Corrective Action Section B			Verification	A	A		
DATE		Section A Initial Action Desc	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			


NOTE: Date & initial all entries



	DESIG	n M	DRAWN BY	DART AEROSPACE LTD				
	V V		KE	VICTORIA INTERNATIONAL AIRPORT, CANADA				
CHECKED		KED_/	APPROVED	DRAWING NO. R	REV. B			
		ny	BW	D2690 SHEET 1	OF 1			
	DATE	***************************************	<u> </u>	TITLE	SCALE			
97.10.02				LANYARD ASSEMBLY	NTS			
	Α		97.07.03	NEW ISSUE				
	B 97.10.02		97.10.02	REVISED NOTE FOR ADDITIONAL LENG	TH			
BI OF O1 08.20			01.08.20	ADD NOTE TO REMOVE 2.25" OF SLEEVE				
B2 -# 04.06.24		- 04.06.24	ADDED TOLERANCE					



DEO's



D2690-X

X = LENGTH IN INCHES

NOTE: CUT CABLE 2.50* INCHES LONGER THAN 'X' LENGTH.

FOLD ENDS TIGHT TO 'X' LENGTH AND CRIMP WITH SLEEVE AT END OF LOOSE END OF CABLE WITH

CBL-705 CRIMPING TOOL.

*ADDITIONAL LENGTH MAY BE NECESSARY IN

SOME APPLICATIONS. CUT AS REQUIRED.

SHOP COPY RETURN TO

FNGINEERING

NOTE: IN SOME CASES, END HAS TO BE CRIMPED AFTERIROLLED COPY

ASSEMBLY WITH ATTACHING PARTS. SUBJECT TO AMENDMENT

WITHOUT NOTICE

Copyright 1997 by DART AEROSPACE LTD